

# Napa Plant Site Week 1 North Unit Breach Salinity Data





Courtesy Ducks Unlimited, October 13, 2008




Courtesy Ducks Unlimited, October 13, 2008









PURPOSE: WETLAND RESTORATION  
 DATUM: NAVD88  
 ADJACENT PROPERTY OWNERS: SEE TABLE 6






FIGURE A-1  
 MONITORING STATIONS  
 IN: CITY OF AMERICAN CANYON  
 AT: 2963 GREEN ISLAND RD.  
 COUNTY OF: NAPA STATE: CA  
 APPLICATION BY: CALIFORNIA

## Initial Stratification - North Unit Breach





## Napa Plant Site North Unit Breach Salinities



## Napa Plant Site North Unit Breach Salinities

